Survey No. T-819

## Maryland Historical Trust State Historic Sites Inventory Form

DOE \_\_yes \_\_no

Magi No.

1. Nam	e (indicate pro	eferred name)		
historic				
and/or common	George Taylor H	ouse		
2. Loca	ation			
street & number	Fairbank Road			not for publication
city, town	Fairbank	vicinity of	congressional distric	ct Fifth
state	MD	county	Talbot	
3. Clas	sification			
Category district _X_ building(s) structure site object	Ownership public private both Public Acquisition in process being considered xnot_applicable	Status  X occupied  unoccupied  work in progress Accessible  yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	' <b>ty</b> (give names a	and mailing addres	sses of <u>all</u> owners)
name Dorli	s and George Jen	sen		
street & number	Fairbank Road		telephone	no.:
city, town	Fairbank	state	and zip code M	D 21671
5. Loca	ation of Leg	al Descripti	on	
courthouse, regi	stry of deeds, etc. Talb	ot County Clerk	of Court	liber <sup>543</sup>
street & number	Talbot County C	ourthouse		folio 22
city, town	Easton		stat	te MD
6. Rep	resentation	in Existing	Historical Su	rveys
title				
date pository for su			federal	state county loca
city, town			stat	de

7. Descri	ption
-----------	-------

Survey No. T-819

Condition  excellent  good	ruins	Check one unaltered altered	Check one	
fair	unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The George Taylor house is located on Fairbank Road in the village of Fairbanks on Tilghman Island. Talbot County, Maryland. The house faces north with the principal gable oriented on an east/west axis.

Built around the turn of the twentieth century, this two-story house is clad in yellow asbestos shingles and covered by an asphalt shingle roof. It is supported by a brick pier foundation.

The four bay house has two doors as the central bays, and two-over-two sash windows as the two outer bays. A screened in porch stretches across the full width of the first floor. Two original turned porch supports are flush against the exterior wall of the house. The windows have plain, wide surrounds, and the extended eaves return onto the east and west elevations. The second floor has four two-over-two sash windows.

The only windows on the east and west elevations are two small twoover-two sash windows at the attic story. An interior brick chimney stands above each gable end.

The south elevation has an enclosed breezeway leading to a one story, gable roofed summer kitchen with an interior chimney at the south gable end. According to the present owners, the summer kitchen was formerly used as a one horse stable separate from the main house, and originally had a board and batten exterior. A screened porch shed addition is connected to the southern end of the summer kitchen. Two two-over-two sash windows light the first floor of the south elevation to the west of the summer kitchen. Four two-over-two sash windows light the second story

The interior was not seen.

1700	istoric	_ archeology-prehistoric _ archeology-historic _ agriculture X architecture	conservation	literature military music t philosophy politics/government	science sculpture social/ humanitarian theater transportation
Specific	dates		Builder/Architect	-	other (specify)
check:	and/o		BX CD	EFG	
	Level o	f Significance: _	nationalstate	X <sub>local</sub>	
Prepare support		summary paragraph o	of significance and	a general statement o	f history and

Survey No. T-819

8. Significance

According to the present owners, George Taylor built this house which later belonged to the Kinnamon family, the Lomax family, and then to Clarence Harrison. Although the front facade has two doors, the house was never used as a two family home. This house is the only Fairbank home with such a double door design.

The George Taylor house is one of a collection of late 19th century. two-story, frame houses which make up the housing stock of Fairbank.

10.	Geographical	Data			•
_	of nominated property			Quadrang	le scale
•	rences do NOT complete	UTM reference	es		
AZone	Easting Northing	لبيا	В	asting	Northing
с			□ L		
E			F L L		
G L			н 💹 👢		
Verbal b	oundary description and jus	stification			
	oundary description and jus	erties overlappi	i <b>ng state or coun</b> county	ty boundaries	code
List all s	tates and counties for prop	erties overlappi code	_	ty boundaries	code
List all s state	tates and counties for prop	erties overlappi code code	county	ty boundaries	
List all s state	tates and counties for prop	erties overlappi code code d By	county		
List all s state state 11.	tates and counties for proportions  Form Prepared	erties overlappi code code d By architectu	county county ural histori		
List all s state state 11. name/title organization	Form Prepared	erties overlappi code code d By architectu	county  county  ural histori  de date	an	code

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438



